



TD30 Flash Instructions

To update the firmware:


1. Unplug the AC Power cord from the unit.
2. Extract the self-extracting file (Defaults to C:\TD30\up1) to your local computer.



3. Connect a 9-pin serial straight through cable (M-F) between COM1 on your computer and the serial port at the rear/bottom of the TD30 display.
4. Run the program "FlashUpgraderNT.exe"
5. Choose "pwSDK_FlashPlus.inf" (it should be automatically selected). Note the required communication settings.



6. Press the "Flash" button to invoke the downloading process.
7. Plug in the AC Power cord then you can see the download begin.



Be aware that you will not see any activity on the TD30 it will only be visible on the utility running on the PC.

Once the flash process completes to 100% and the Flash utility stops remove the serial cable. The TD30 Display firmware has not been updated successfully.